

FAR 91.207 should be updated to cover the new 406MHZ ELT.  
The change should include a requirement to actually decode and read the 406MHZ ELT's transmission of its I.D. number and GPS Latitude and longitude by independent Test Equipment to verify that the 406MHZ ELT is actually transmitting the correct I.D. number and the actual Lat/Long thru the ELT Antenna.